




US Army Corps
of Engineers
Savannah District

Rainfall

Savannah River Basin Fact Sheet



*Rainfall deficit for 2007 are through October.

The average annual rainfall in the Hartwell, Russell, and Thurmond Basins is 51.7 inches, 47.2 inches, and 46.4 inches, respectively.

During the drought which started in March 2006, rainfall has significantly below normal. This has resulted in reduced inflows into the lakes and lower than normal lake levels.

From March 2006 through October 2007, deficits by basin are: Hartwell = 40.3 inches, Russell = 25 inches, and Thurmond = 22.4 inches.

Hartwell Dam & Lake

P.O. Box 278
5625 Anderson Highway
Hartwell, GA 30643-0278
706-856-0300
1-888-893-0678
www.sas.usace.army.mil/lakes/hartwell

Richard B. Russell Dam & Lake

4144 Russell Dam Drive
Elberton, GA 30635-9271
706-213-3400
1-800-944-7207
www.sas.usace.army.mil/lakes/russell

J. Strom Thurmond Dam & Lake

Rt. 1, Box 12
Highway 221
Clarks Hill, SC 29821-9703
864-333-1100
1-800-533-3478
www.sas.usace.army.mil/lakes/thurmond